

Machine Id VOLVO A40G 752088

Component Drop Box

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP450806		
	Sample Date		Client Info		13 Jun 2024		
	Machine Age	hrs	Client Info		1460		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	94		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	<1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	4		
	Lead	ppm	ASTM D5185m	>30	0		
	Copper	ppm	ASTM D5185m	>30	10		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	20		
Moderate concentration of visible dirt/debris present in the oil.	Potassium	ppm	ASTM D5185m	>20	3		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	▲ MODER		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		12		
	Boron	ppm	ASTM D5185m	111	69		
The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		6		
	Manganese	ppm	ASTM D5185m		3		
	Magnesium	ppm	ASTM D5185m	39	<1		
	Calcium	ppm	ASTM D5185m		54		
	Phosphorus	ppm	ASTM D5185m		2250		
	Zinc	ppm	ASTM D5185m		83		

Sulfur


Visc @ 40°C

ppm ASTM D5185m 20179

ASTM D445 333

29033

48.4





Certificate L2367

Laboratory Sample No.

: VCP450806 Lab Number : 06215113 Unique Number : 11087977 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 19 Jun 2024 : 20 Jun 2024 Diagnosed : 21 Jun 2024 - Sean Felton

ALTA EQUIPMENT COMPANY 5151 DR MARTIN LUTHER KING BLVD

FORT MYERS, FL US 33905 Contact: TODD LARK

tlark@altaequipfl.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (239)481-3302

Contact/Location: TODD LARK - VOLVO0090