

WEAR CONTAMINATION FLUID CONDITION


ABNORMAL NORMAL NORMAL



Machine Id **VOLVO A40G 752086**

Transmission (Auto)

VOLVO AUTOMATIC TRANSM	ISSION FLU	ID AT	102 (GAL)			
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. We recommend an early resample to monitor this condition.	Sample Number		Client Info		VCP450876		
	Sample Date		Client Info		14 Jun 2024		
	Machine Age	hrs	Client Info		1298		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	38		
The nickel level is abnormal. Moderate concentration of visible metal present.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m		<u>^</u> 9		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>50	22		
	Lead	ppm	ASTM D5185m	>50	<1		
	Copper	ppm	ASTM D5185m	>225	56		
	Tin	ppm	ASTM D5185m	>10	7		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	▲ MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	nnm	ASTM D5185m	>20	14		
	Potassium	ppm	ASTM D5185m		3		
There is no indication of any contamination in the fluid.	Water	ppm	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		6		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	187	78		
	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		6		
	Magnesium	ppm	ASTM D5185m	6.8	<1		
	Calcium	ppm	ASTM D5185m	215	69		
	Phosphorus	ppm	ASTM D5185m	445	190		
	Zinc	ppm	ASTM D5185m	56	8		
	Sulfur	ppm	ASTM D5185m	1336	1797		
	Visc @ 40°C	cSt	ASTM D445	35.3	28.1		







Certificate L2367

Laboratory Sample No.

: VCP450876 Lab Number : 06215196 Unique Number : 11088060 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 19 Jun 2024 : 20 Jun 2024 Diagnosed : 21 Jun 2024 - Sean Felton

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL

US 33905 Contact: TODD LARK

tlark@altaequipfl.com

ALTA EQUIPMENT COMPANY

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (239)481-3302