**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 


[W9019]

## **JOHN DEERE H1590586**

**Differential** 

JOHN DEERE GI -5 80W90 (2 GAL)

JOHN DEERE GL-5 80W90 (2 GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. ( Customer Sample Comment: W9019)	Sample Number		Client Info		JR0197075		
	Sample Date		Client Info		18 Jun 2024		
	Machine Age	hrs	Client Info		3529		
	Oil Age	hrs	Client Info		3529		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	PQ		ASTM D8184		31		
	Iron	ppm	ASTM D5185m	>500	273		
Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185m		3		
	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	1		
	Lead	ppm	ASTM D5185m		203		
	Copper	ppm	ASTM D5185m		112		
	Tin	ppm	ASTM D5185m		3		
	Vanadium	ppm	ASTM D5185m	, , ,	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	19		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	1		
	Water		WC Method	>.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		14		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		11		
	Barium	ppm	ASTM D5185m		7		
	Molybdenum	ppm	ASTM D5185m		12		
	Manganese	ppm	ASTM D5185m		7		
	Magnesium	ppm	ASTM D5185m		20		
	Calcium	ppm	ASTM D5185m		48		
	Phosphorus	ppm	ASTM D5185m		2008		
	Zinc	ppm	ASTM D5185m		49		
	Sulfur	ppm	ASTM D5185m		37261		





Laboratory Sample No. Lab Number Unique Number : 11088856

: 06215992

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0197075

Received **Tested** Diagnosed

: 20 Jun 2024 : 22 Jun 2024 : 23 Jun 2024 - Don Baldridge

JRE - NEW BERN 3816 MARTIN LUTHER KING BLVD

NEW BERN, NC US 28562

Test Package : MOBCE ( Additional Tests: PQ ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: NEW BERN SHOP nick.etherdridge@jamesriverequipment.com;canastasio@wearcheckusa.com T:

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: