WEAR CONTAMINATION FLUID CONDITION

SEVERE NORMAL NORMAL



Machine Id **CATERPILLAR 930K C335137 (S/N 0RHN02111)**

Component
Rear Axle


DECOMMENDATION -					(_)		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.	Sample Number		Client Info		JR0218774		
	Sample Date	1	Client Info		14 Jun 2024		
	Machine Age	hrs	Client Info		8654		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		Ohammad		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				SEVERE		
WEAR	PQ		ASTM D8184		71		
Bearing and/or bushing wear is indicated.	Iron	ppm	ASTM D5185m	>500	256		
	Chromium	ppm	ASTM D5185m	>10	2		
	Nickel	ppm	ASTM D5185m	>10	3		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>25	△ 65		
	Lead	ppm	ASTM D5185m	>25	2		
	Copper	ppm	ASTM D5185m	>50	A 760		
	Tin	ppm	ASTM D5185m	>10	2		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	10		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		10		
	Water	PP	WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	LIGHT		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The oil is no longer serviceable as a result of the abnormal and/or severe wear.	Boron	ppm	ASTM D5185m		1		
	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		4		
	Magnesium	ppm	ASTM D5185m		12		
	Calcium	ppm	ASTM D5185m		3006		
	Phosphorus	ppm	ASTM D5185m		1032		
	riiospiiorus	PPIII	710111120100111				
	Zinc	ppm	ASTM D5185m		1210		

Visc @ 40°C

cSt

ASTM D445

83.7





Certificate L2367

Laboratory

Sample No.

: JR0218774 Lab Number : 06218535

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

Unique Number : 11096732 Diagnosed Test Package : CONST (Additional Tests: PQ)

: 25 Jun 2024 : 26 Jun 2024 - Sean Felton

: 24 Jun 2024

JRE - ASHEVILLE 101 BRUCE DRIVE ASHEVILLE, NC US 28806

Contact: Randy Warren randy.warren@jamesriverequipment.com

T: (528)667-0176 F: (828)667-4865

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: Randy Warren - VANASH