WEAR CONTAMINATION **FLUID CONDITION** **ABNORMAL** NORMAL **NORMAL**



Machine Id Marie LIEBHERR R924CHDSL 008931-645


Component Right Final Drive Fluid NAPA 80W90 (GAL)					.,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. We recommend an early resample to monitor this condition.	Sample Number		Client Info		LHMC131948		
	Sample Date		Client Info		18 Jun 2024		
	Machine Age	hrs	Client Info		7718		
	Oil Age	hrs	Client Info		50		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	24		
Moderate concentration of visible metal present. All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	1		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m		4		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	▲ MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	15		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		10		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		2		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		6		
	Calcium	ppm	ASTM D5185m		23		
	Phosphorus	ppm	ASTM D5185m		638		
	Zinc	ppm	ASTM D5185m		18		

ppm

Sulfur

ASTM D5185m

18096





Certificate L2367

Laboratory Sample No.

: LHMC131948 Lab Number : 06220436 Unique Number : 11098633

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 25 Jun 2024 **Tested**

: 26 Jun 2024 Diagnosed

: 27 Jun 2024 - Jonathan Hester

PORTAGE, WI US 53901 Contact: RUSTY rusty.curtis1@gmail.com T: (608)697-3494

CURTIS EXCAVATING

N8701 HWY EE

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)