

Store 9 - Marietta

JOHN DEERE 460E 1DW460ETELF706102

Diesel Engine

{not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Check for low coolant level. We advise that you check for the source of the coolant leak. We recommend an early resample to monitor this condition.	Sample Number		Client Info		LEC0050946		
	Sample Date		Client Info		14 Jun 2024		
	Machine Age	hrs	Client Info		7608		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR All component wear rates are normal.	Iron	ppm	ASTM D5185m	>51	5		
	Chromium	ppm	ASTM D5185m	>11	0		
	Nickel	ppm	ASTM D5185m	>5	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>3	0		
	Aluminum	ppm	ASTM D5185m	>31	2		
	Lead	ppm	ASTM D5185m	>26	2		
	Copper	ppm	ASTM D5185m	>26	6		
	Tin	ppm	ASTM D5185m	>4	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m		6		
Sodium and/or potassium levels are high.	Potassium	ppm	ASTM D5185m		▲ 95		
	Fuel		WC Method		<1.0		
	Water	<u> </u>	WC Method	>0.21	NEG		
	Glycol	%	*ASTM D2982	0	NEG		
	Soot %	%	*ASTM D7844		0.1		
	Nitration	Abs/cm	*ASTM D7624	>20	5.1		
	Sulfation	Abs/.1mm	*ASTM D7415		17.6		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.21	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>31	195		
The BN result indicates that there is suitable alkalinity remaining in the oil.	Boron	ppm	ASTM D5185m		12		
	Barium	ppm	ASTM D5185m		<1		
	Molybdenum	ppm	ASTM D5185m		62		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		379		
	Calcium	ppm	ASTM D5185m		1662		
	Phosphorus	ppm	ASTM D5185m		1013		
	Zinc	ppm	ASTM D5185m		1205		
	Sulfur	ppm	ASTM D5185m		3823		
	Oxidation		*ASTM D7414	>25	12.6		


Base Number (BN) mg KOH/g ASTM D2896

ASTM D445

Visc @ 100°C cSt

11.2

13.7



HAYDEN EXCAVATING Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Received PO BOX 766 : LEC0050946 : 26 Jun 2024 È Lab Number : 06220838 Tested WAYNESBURG, PA : 27 Jun 2024 Unique Number : 11099035 Diagnosed : 27 Jun 2024 - Sean Felton US 15370 Test Package : CONST (Additional Tests: Glycol, TBN) Contact: ROBBIE Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. rts2577@yahoo.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

Contact/Location: ROBBIE ? - HAYWAYPA Page 2 of 2