WEAR CONTAMINATION FLUID CONDITION

NORMAL

ABNORMAL


NORMAL

[SWO072947]

VOLVO EC480EL 315428

Left Swing Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP443969	VCP447589	
	Sample Date		Client Info		21 Jun 2024	19 Dec 2023	
	Machine Age	hrs	Client Info		1013	482	
	Oil Age	hrs	Client Info		0	0	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		N/A	Not Changd	
	Filter Changed		Client Info		Not Changd	Not Changd	
	Sample Status				ABNORMAL	ABNORMAL	
WEAR	Iron	ppm	ASTM D5185m	>1200	92	381	
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1	6	
	Nickel	ppm	ASTM D5185m		0	0	
	Titanium	ppm	ASTM D5185m		0	<1	
	Silver	ppm	ASTM D5185m		0	0	
	Aluminum	ppm	ASTM D5185m	>25	<1	3	
	Lead	ppm	ASTM D5185m	>50	0	0	
	Copper	ppm	ASTM D5185m	>50	12	▲ 56	
	Tin	ppm	ASTM D5185m	>10	0	0	
	Vanadium	ppm	ASTM D5185m		0	<1	
	White Metal	scalar	*Visual	NONE	LIGHT	MODER	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>100	10	21	
	Potassium	ppm	ASTM D5185m		<1	0	
Moderate concentration of visible dirt/debris present in the oil.	Water	la la	WC Method	>0.25	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	▲ MODER	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.25	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0	<1	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	106	0	
	Barium	ppm	ASTM D5185m		<1	3	
	Molybdenum	ppm	ASTM D5185m	12	8	0	
	Manganese	ppm	ASTM D5185m		1	7	
	Magnesium	ppm	ASTM D5185m	12	44	0	
	Calcium	ppm	ASTM D5185m	150	137	8	
	Phosphorus	ppm	ASTM D5185m	1650	811	321	
	Zinc	ppm	ASTM D5185m	125	124	38	
	Sulfur	ppm	ASTM D5185m	22500	22546	15456	
	Visc @ 40°C	cSt	ASTM D445	000	247	174	





Certificate L2367

Laboratory Sample No.

: VCP443969 Lab Number : 06221593 Unique Number : 11099790 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 Jun 2024 **Tested** : 27 Jun 2024

: 28 Jun 2024 - Angela Borella Diagnosed

SAIIA CONSTRUCTION LLC 4400 LEWISBURG RD BIRMINGHAM, AL

US 35207

Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268 F: (205)943-2269

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)