


CORROSION CONTAMINANTS COOLANT CONDITION **NORMAL NORMAL NORMAL**

BOWERMAN - ORANGE COUNTY CA SUTTON STROMART BOW 2 Component Coolant

CHEVRON DELO EXTENDED LIFE COOLANT (--- GAL)

	GAL)				-		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. The fluid is suitable for further service.	Sample Number		Client Info		WC0848341	WC0848267	WC0848284
	Sample Date		Client Info		25 Jun 2024	29 Mar 2024	11 Jan 202
	Machine Age	hrs	Client Info		66097	0	0
	Oil Age	hrs	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL	NORMAL	NORMAL
CORROSION	Total Dissolved Solids				445.0	491.5	419.5
	Coolant Appearance		*Visual	Clear	normal	normal	normal
CONTAMINANTS	Boiling Point	°C	WC Method		233	230	
There is no indication of any contamination in the coolant.	Specific Gravity		*ASTM D1298		1.083	1.080	1.081
	рН	Scale 0-14	ASTM D1287		7.43	7.05	6.82
	Nitrites	ppm	AP-053:2009		NT	NT	NT
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		64.0	60.6	61.2
	Freezing Point	°F	ASTM D3321		-63	-57	-59
	Carboxylate				fail	fail	fail
	Coolant Color		*Visual		Red	Red	Red





Certificate L2367

Laboratory Sample No.

: WC0848341 Lab Number : 06223071

Unique Number: 11101268

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Jun 2024 **Tested**

: 01 Jul 2024 Diagnosed

: 01 Jul 2024 - Jonathan Hester Test Package : COOL- (Additional Tests: GlycolType, TAN Man, TBN)

MONTAUK ENERGY CAPITAL LLC (TEXAS) LP 1412 N SAM HOUSTON PKWY E, SUITE 100 HOUSTON, TX US 77032

Contact: DAMON MCCLENAN dmcclenan@montaukenergy.com T: (713)781-1126

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (713)781-1127