

RECOMMENDATION

NORMAL WEAR CONTAMINATION NORMAL **FLUID CONDITION** NORMAL

OIL ANALYSIS REPORT

Area

[A35845] JOHN DEERE 310E 1T0310ELKJG338907

Rear Rear Left Final Drive

JOHN DEERE HY-GARD HYDRAULIC/RANSMISSION (2 GAL)

Resample at the next service interval to monitor. (Customer Sample Comment: A35845)

/E	7 -	R

Metal levels are typical for a new component breaking in.

CONTAMINATION


There is no indication of any contamination in the oil.


	FL	UID	CON	IDITION	
--	----	-----	-----	----------------	--

The condition of the oil is acceptable for the time in service.

	31113	5101V (2	GAL			
Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WE0007711		
Sample Date		Client Info		16 Jul 2024		
Machine Age	hrs	Client Info		2196		
Oil Age	hrs	Client Info		2196		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		N/A		
Sample Status				NORMAL		
			4050			
PQ		ASTM D8184	>1250	293		
Iron	ppm	ASTM D5185m	>750	730		
Chromium	ppm	ASTM D5185m	>9	3		
Nickel	ppm	ASTM D5185m	>10	2		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	10	<1		
Aluminum	ppm	ASTM D5185m	>40	4		
Lead	ppm	ASTM D5185m	>15	0		
Copper	ppm	ASTM D5185m	>40	117		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		<1		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>75	12		
Potassium	ppm	ASTM D5185m	>20	2		
Water		WC Method	>0.075	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.075	NEG		
Sodium	ppm	ASTM D5185m	>51	0		
Boron	ppm	ASTM D5185m		3		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		4		
Manganese	ppm	ASTM D5185m		6		
Magnesium	ppm	ASTM D5185m		100		
Calcium	ppm	ASTM D5185m		3698		
Phosphorus	ppm	ASTM D5185m		1095		
Zinc	ppm	ASTM D5185m		1269		
Sulfur	ppm	ASTM D5185m		3670		
Visc @ 40°C	cSt	ASTM D445	59	53.3		

Submitted By: BOBBY LUCKY





WARRIOR TRACTOR AND EQUIPMENT - HUNTSVILLE Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : WE0007711 Received 25135 ONE AVIATION WAY SW : 18 Jul 2024 Śè MADISON, AL Lab Number : 06240584 Tested : 19 Jul 2024 Unique Number : 11129418 Diagnosed : 20 Jul 2024 - Don Baldridge US 35756 Test Package : CONST (Additional Tests: PQ) Contact: BOBBY LUCKY Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. warriorparts033@gmail.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: F: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: BOBBY LUCKY Page 2 of 2