LABORATORY ANALYSIS



11525 Rock Island Court, St. Louis, MO 63043 Tel: 1-800-876-0008 info@englube.com

PLANET TOOL & ENGINEERING

315 COOL SPRINGS ROAD

O`FALLON, MO US 63366

Contact: Dave Diedrich ddiedrich@planet-tool.com

T: (636)379-9800

F:

Department GRINDING ROOM

Equipment No. ACC Okamoto (X0007)

System Machining Fluid

Oil Type ENGINEERED LUBRICANTS ENCOOL SOL-305MGLL (30 GAL)

SAMPLE INFORMATION

DIAGNOSIS

Inspect the reservoir for settled chips/fines, tramp oils, physical growth and remove them before there is an accumulation. Add a "severe" dose of BioTech 084, 3.3 ounces to the tank side reservoir in an area of high agitation. Follow up three days later with a "maintenance" dose, 0.8 ounces, to stabilize the microbial additive package. Circulate the coolant daily for proper aeration.{not applicable} Excessively high bacteria counts. Elevated yeast counts. Excessively high mold counts. The condition of the machining fluid is suitable for service.

SAMPLE INFORMATION					
Lab Number	N	lew	2307-00255	2305-00421	2303-00057
Date of Sample	(7	Typical)	07 Jul 2023	08 May 2023	06 Mar 2023
Oil Added			UNK	UNK	UNK
Last Drain Date					
Months on Sample			69.9	67.9	65.9
Last Filter Service					
Sample Point					
Sample Status			SEVERE	SEVERE	SEVERE
RATIO PER REFRACTOMETER					
	11/10101	/IE I E I I	2.3	2.4	2.5
Refract. Reading Refract. Model			DIGITAL	DIGITAL	DIGITAL
	alluvatav				
Refract. Ratio	oil:water		■12:1	□12:1	■11:1
PH (ASTM E-70)					
рН	Scale 0-14		■8.8	■8.9	■ 8.8
Ratio Rec'd	oil:water		AS REC'D	AS REC'D	AS REC'D
BACTERIA COUNT (CLASS RANGE 0 TO 6)					
Bacteria Class	Scale 0-6		6	• 6	0
FUNGUS COUN	T (CLASS	S RANGES	: YEAST 0 TO 4	MOLD 0 TO 3)	
Yeast Class	Scale 0-4		3	<u>^</u> 2	□ 0
Mold Class	Scale 0-3		3	<u>^</u> 2	• 3

Customer Id: ENC0303701 Sample No.: EN23070255 Lab Number: 23070255 Test Package: TEST



To manage this report scan the QR code

To discuss the diagnosis or test data: Brad Fritz +1 (314)872-9540 bfritz@englube.com

To change component or sample information: Tracy Weaks +1 (314)872-9540 tweaks@englube.com



FUEL REPORT





