

## 04960495

Customer: WEARCHECK USA 501 Madison Ave Cary, NC 27513 USA

Attn: CATHERINE ANASTASIO

Tel: E-Mail:

CANASTASIO@WEARCHECKUSA.CO

System Information

System Volume: 0 gal Bulk Operating Temp: Not Specified

Heating Source:

Blanket:

Fluid: HEAT TRANSFER FLUID ISO 68

Make:

Sample Information

Lab No: 02350195

Analyst: Bill Quesnel CLS, OMA II, MLA-

III,LLA-I


Sample Date: 04/22/20 Received Date: 04/23/20 Completed: 04/24/20

Bill Quesnel CLS,OMA II,MLA-III,LLA-I

Recommendation: Recommend vent tank to reduce light ends. This product is at the end of it's life, recommend schedule a fluid changeout.

Comments: Acid Number (AN) is severely high. (GCD) 90% Distillation Point is severely high. Calcium ppm levels are abnormally high. COC Flash Point is marginally low. (GCD) 10% Distillation Point is marginally low.





WearCheck Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it.