





## **APP-TOX**

## Customer: PTRHTF10059

CERTAINTEED - SAINT GOBAIN 11519 US RT 250 N MILAN, OH 44846 USA

Attn: DAVE BLAKELY Tel: (419)541-0843

E-Mail: dave.l.blakely@saint-gobain.com

### **System Information**

System Volume: 8875 gal

Bulk Operating Temp: 500F / 260C

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO AF

Make: JOHN ZINK

### Sample Information

Lab No: 02473038 Analyst: Yvette Trzcinski Sample Date: 02/07/22 Received Date: 02/18/22 Completed: 02/23/22 Yvette Trzcinski


yvette.trzcinski@hollyfrontier.com

Recommendation: Flash point, GCD boiling points, solids and viscosity as well as acid number have remained consistent from the last sample. In large systems when acid number is around 0.3 we recommend sweetening the system with new fluid. resample in 6 months

Comments: Acid Number (AN) is abnormally high. (GCD) 90% Distillation Point is marginally high.







# Flash point and viscosity are within acceptable ranges, the acid number has improved from the last sample as well as the solids amount - looks like there was

o9/17/21 some make up added to the system. The GDC 90% is slightly high but is fairly consistent over the last 3 samples. Product is acceptable for continued use and resample in 6 - 12 months. Acid Number (AN) is abnormally high. (GCD) 90% Distillation Point is marginally high.

The total acid number is high but the acid number and GCD 90% and flash point have remained consistent from the last sample. The solids have more than doubled and there is a slight increase in viscosity which could be due to degradation in the system and contamination. Continue to monitor and resample in 6

**Historical Comments** 

doubled and there is a slight increase in viscosity which could be due to degradation in the system and contamination. Continue to monitor and resample in 6 months

This is a new system that was brought on line in December 2019 - filled with new Calflo AF heat transfer oil. The total acid number is very high for oil that has been in service for 7 - 8 months. The viscosity flash point are acceptable for service. the system was not flushed before filling with the fluid, please resample in 3-4 months to monitor the system Acid Number (AN) is abnormally high. (GCD) 90% Distillation Point is marginally high.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.

07/28/20