

[15-12-50-21W5] TOURMALINE BANSHEE 5500-2

Customer: PTRHTF60079

Tourmaline 15-12-50-21W5

Edson, AB T7E 1R8 CA Attn: Justin Thebeau

Tel: E-Mail:

justin.thebeau@tourmalineoil.com

System Information

System Volume: 20000 ltr

Bulk Operating Temp: 482F / 250C

Heating Source:

Blanket:

Fluid: PETRO CANADA PETRO-THERM

Make: RUSHTON

Sample Information

Lab No: 02626251 Analyst: Clinton Buhler Sample Date: 04/01/24 Received Date: 04/02/24 Completed: 04/30/24


Clinton Buhler


Clinton.Buhler@HFSinclair.com


Recommendation: Sample results indicate the fluid is severely and degraded and the system is fouled with high solids content, going from 1.11% to 2.57% in less than 3 months. Acid number is well past the condemnable limit (due to fluid oxidation) and likely has caused system corrosion, judging by the increase in Iron content at 36 ppm. Fluid needs to be replaced and the system requires a cleaning and flush to remove the excess solids (degradation byproducts.) Petro-Canada Lubricants can assist with providing guidance on the cleaning process using Calflo Cleaning Fluid followed by a flush with Calflo Flushing Fluid. After fluid replacement, please ensure that expansion tank blanket gas is operational to prevent future oxidation.


Comments: Pentane Insolubles levels are severely high. Acid Number (AN) is severely high. Visc @ 40°C is severely high. (GCD) 90% Distillation Point is marginally high.












Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

0

Baseline Data



Historical Comments	
01/20/24	There appears to be a significant change in the fluid viscosity, acidity and pentane insolubles in 8 months time. This would be severe degradation in that short period of time. Resample the unit, ensure the sample point is purged adequately and the sample is representative of the whole system. If equipped the pump discharge line is an ideal place to collect the sample; low point drains can collect settled materials and may not be representative of the whole system if not purged well. Pentane Insolubles levels are severely high. Acid Number (AN) is severely high. Visc @ 40°C is severely high. (GCD) 90% Distillation Point is marginally high.
05/09/23	Sample results indicate that the fluid is in good condition and is suitable for continued service. Resample in 12 months.
07/05/22	Sample results indicate that the fluid is in very good condition and is suitable for continued service. Resample in 12 months. If possible please include time on oil when filling out analysis request forms.
02/08/21	Fluid remains in excellent condition. Continue to submit samples annually to proactively monitor fluid condition.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.