

HEATER 3

Customer:

ASSOCIATED ASPHALT 195 LAWSON FORK ROAD INMAN, SC 29349 USA

Attn: MARSHALL HOWINGTON

Tel: (864)472-2816

E-Mail:

mhowington@associatedasphalt.com

System Information

System Volume: 0 gal

Bulk Operating Temp: Not Specified

Heating Source:

Blanket:

Fluid: NOT GIVEN

Make:

Sample Information

Lab No: 05176321 Analyst: Doug Bogart Sample Date: 02/01/21 Received Date: 02/05/21 Completed: 02/19/21

Doug Bogart


dougb@wearcheckusa.com

Recommendation: This is a baseline read-out on the submitted sample.

Comments: All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the fluid. The AN level is acceptable for this fluid.







Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

GCD Spectrum

| Historical Comments | |
|---------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

WearCheck Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it.