



LIEBHERR L586 71616 - Transmission (Auto)

Sample No: LH0274523 **Oil Type:** NOT GIVEN

SAMPLE INFORMATION

Sample Number	LH0274523	LH0256667	 	
Sample Date	20 Aug 2023	17 Apr 2023	 	
Machine Hours	2389	1042	 	
Oil Hours	0	0	 	
Oil Changed	Changed	Changed	 	
Sample Status	NORMAL	NORMAL	 	
	N			
Visc @ 40°C cSt	37.4	93.0	 	

CONTAMINATION Silicon ppm 09 8 🔘 Sodium ppm 06 021 0 <1 Potassium ppm

Ä				
WEA	R METALS			
			0.40	
Iron	ppm	0 25	0 12	
Copper	ppm	02	02	
Lead	ppm	0	○ <1	
Tin	ppm	0	0	
Aluminum	ppm	02	○ <1	
Chromium	ppm	0	0	
Molybdenum	ppm	0	0	
Nickel	ppm	○ <1	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	<1	○ <1	
Vanadium	ppm	0	0	



DOFASCO INC.

P.O. BOX 2460, 1330 BURLINGTON ST.E, HEAVY EQUIPMENT REPAIR HAMILTON, ON CA L8N 3J5 Contact: HAROLD LOUDEN harold.louden@arcelormittal.com T: (905)548-7200 F: (905)548-7465

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

٥

ADDITIVES Calcium 3621 ppm 0 3361 Magnesium ppm 9 $\bigcirc 7$ Zinc 1453 1390 ppm 1281 Phosphorus 0 1259 ppm Barium ppm 0 0 Boron 117 ppm 0 109


Depot: DOFHAM Unique No: 5630282 Kevin Marson Signed: **Report Date:** 21 Aug 2023





GRAPHS

 $\overline{\mathbf{O}}$



Report Id: DOFHAM [WCAMIS] 02577222 (Generated: 08/21/2023 16:05:32) Rev: 1

Contact/Location: HAROLD LOUDEN - DOFHAM