LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 145585-1217 - Splitter Box

Sample No: LH0259482

Magnesium

Phosphorus

Zinc

Barium

Boron

Oil Type: GEAR OIL SAE 75W90

U SAM	PLE INF	DRMATION		
Sample Number		LH0259482	 	
Sample Date		23 Aug 2023	 	
Machine Hours		1112	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OILC	ONDITIO	ON		
Visc @ 40°C	cSt	120	 	
ada .				
CON	TAMINA	TION		
	I AMIII F			
Silicon	ppm	() <1	 	
Sodium	ppm	3	 	
Potassium	ppm	1	 	
	R META			
Iron	ppm	0 16	 	
Copper	ppm	O <1	 	
Lead 	ppm	0 0	 	
Tin	ppm	0 0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0 0	 	
Molybdenum	ppm	0	 	
Vickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Vanganese	ppm	○ <1	 	
Vanadium	ppm	0	 	
ADD				
ADD	ITIVES			
Calcium	ppm	13	 	



RICHMOND STEEL RECYCLING

11760 MITCHELL ROAD RICHMOND, BC CA V6V 1V8

Contact: Aaron Kaetler AKaetler@richmondsteel.ca

T:

F: (604)324-8617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIC117RICUnique No:5642596Signed:Wes DavisReport Date:11 Sep 2023

3

20

0

1431

173

ppm

ppm

ppm

ppm

ppm

LIEBHERR







GRAPHS

