# LIEBHERR

# **CONSTRUCTION EQUIPMENT**

# **056328-1783-Swing Drive**





Sample Status

### **OIL CONDITION**

NORMAL

	CONTA	MINATIO	N
Silicon		ppm	0

Silicon	ppm	<b>3</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>1</b>	 	



## **WEAR METALS**

Iron	ppm	<b>431</b>	 	
Copper	ppm	<b>60</b>	 	
Lead	ppm	<b>2</b>	 	
Tin	ppm	<b>3</b>	 	
Aluminum	ppm	<b>○</b> <1	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>2</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>4</b>	 	
Vanadium	ppm	0	 	



#### ADDITIVE

Calcium	ppm	<b>16</b>	 	
Magnesium	ppm	<b>1</b>	 	
Zinc	ppm	<b>23</b>	 	
Phosphorus	ppm	<b>1785</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>7</b>	 	





#### **American Iron and Metal**

10305 Metropolitaine Est, Garage porte 13 Montreal, QC CA H1B 1A1

Contact: Sebastien Liautaud sliautaud@aimrecyclinggroup.com

T: F:

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LACMON
Unique No: 5644735
Signed: Wes Davis
Report Date: 19 Sep 2023

# LIEBHERR

## CONSTRUCTION EQUIPMENT





## **GRAPHS**

