LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0281075 Oil Type: SAE 5W30





Liebherr Canada 140 - 21320 Gordon Way Richmond, BC CA V6W 1J8

Contact: Kendra Curtis kendra.curtis@liebherr.com

T: (604)207-4551 F: (604)270-3254

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Aluminum	ppm	U I	0 2		
Chromium	ppm	0	O <1	 	
Molybdenum	ppm	61	98	 	
Nickel	ppm	0 <1	0	 	
Titanium	ppm	0	O 0	 	
Silver	ppm	0	O <1	 	
Manganese	ppm	0	O <1	 	
Vanadium	ppm	0	0	 	
variadiani	PPIII		ŭ		
	ITIVES				
		○ 843	0 1271	 	
ADD	ITIVES			 	
ADD	ITIVES		O 1271		
ADD Calcium Magnesium	ppm ppm	⊗ 843⊗ 1101	① 1271 899	 	

Depot:LIERICUnique No:5709788Signed:Kevin MarsonReport Date:15 Jan 2024

ppm

60

Boron

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

