## LIEBHERR

## **CONSTRUCTION EQUIPMENT**

### 145586-1218 - Rear Differential

Sample No: LH0269260

Oil Type: GEAR OIL SAE 80W90



| Visc @ 40°C   | cSt | <b>140</b> |  |  |  |  |
|---------------|-----|------------|--|--|--|--|
| **            |     |            |  |  |  |  |
| CONTAMINATION |     |            |  |  |  |  |
| Water         | %   | NEG        |  |  |  |  |

| CONTAMINATION |     |             |  |  |  |  |
|---------------|-----|-------------|--|--|--|--|
| Water         | %   | NEG         |  |  |  |  |
| Silicon       | ppm | <b>6</b>    |  |  |  |  |
| Sodium        | ppm | <b>4</b>    |  |  |  |  |
| Potassium     | ppm | <b>○</b> <1 |  |  |  |  |
|               |     |             |  |  |  |  |

| WEAR METALS |     |              |  |  |  |
|-------------|-----|--------------|--|--|--|
| Iron        | ppm | <b>17</b>    |  |  |  |
| Copper      | ppm | <b>12</b>    |  |  |  |
| Lead        | ppm | <b>()</b> <1 |  |  |  |
| Tin         | ppm | <b>0</b>     |  |  |  |
| Aluminum    | ppm | <b></b> <1   |  |  |  |
| Chromium    | ppm | <b>0</b>     |  |  |  |
| Molybdenum  | ppm | <b>()</b> <1 |  |  |  |
| Nickel      | ppm | <b>0</b>     |  |  |  |
| Titanium    | ppm | 0            |  |  |  |
| Silver      | ppm | 0            |  |  |  |
| Manganese   | ppm | <b>()</b> <1 |  |  |  |
| Vanadium    | ppm | 0            |  |  |  |

| ADDITIVES  |     |             |  |  |  |
|------------|-----|-------------|--|--|--|
| Calcium    | ppm | <b>88</b>   |  |  |  |
| Magnesium  | ppm | <b>2</b>    |  |  |  |
| Zinc       | ppm | <b>23</b>   |  |  |  |
| Phosphorus | ppm | <b>1663</b> |  |  |  |
| Barium     | ppm | <b>2</b>    |  |  |  |
| Boron      | ppm | <b>84</b>   |  |  |  |





#### **American Iron and Metal**

10305 Metropolitaine Est, Garage porte 13 Montreal, QC CA H1B 1A1

Contact: Sebastien Liautaud sliautaud@aimrecyclinggroup.com

T: F:

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LACMON
Unique No: 5721672
Signed: Wes Davis
Report Date: 31 Jan 2024

# LIEBHERR

### CONSTRUCTION EQUIPMENT





#### **GRAPHS**

