CONSTRUCTION EQUIPMENT

[MENARD] LIEBHERR HS855 184638 - Swing Drive

Sample No: LH0291246

Oil Type: **GEAR OIL SAE 80W90**

Sample Information					
Sample Number		LH0291246			
Sample Date		02 May 2024			
Machine Hours		15916			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
Oil Co	ndition				
Visc @ 40°C	cSt	195			
-L	331	O 100			
	• -•				
Conto	amination				
Water	%	NEG			
Silicon	ppm	2			
Sodium	ppm	3			
Potassium	ppm	0 1			
(O) Wood	r Metals				
	Meidis				
Iron	ppm	91			
Copper	ppm	○ <1			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	() <1			
Chromium	ppm	1			
Molybdenum	ppm	0			
Nickel	ppm	0 <1			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	2			
Vanadium	ppm	0			
Addi	lives				
7101011		0.00			
Calcium	ppm	30			
Magnesium	ppm	0 <1			
Zinc	ppm	19			
Phosphorus	ppm	0 1045			
Barium	ppm	1			



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS Unique No: 5775084 Signed: Wes Davis Report Date: 07 May 2024

Contact/Location: Steve Lehto - LIEMIS

ppm

Boron

CONSTRUCTION EQUIPMENT





Graphs

