

LIEBHERR

CONSTRUCTION EQUIPMENT



[MENARD] LIEBHERR HS855 184638 - Boom Hoisting Gearbox

Sample No: LH0291241

Oil Type: GEAR OIL LS 80W90



LIEBHERR CANADA LTD.
 1015 SUTTON DRIVE
 BURLINGTON, ON
 CA L7L 5Z8
 Contact: Steve Lehto
 steve.lehto@liebherr.com
 T: (905)319-9222
 F: (905)319-6617



Sample Information

Sample Number	LH0291241	---	---	---
Sample Date	02 May 2024	---	---	---
Machine Hours	15916	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



Oil Condition

Visc @ 40°C	cSt	● 178	---	---	---
-------------	-----	-------	-----	-----	-----



Contamination

Water	%	● 0.005	---	---	---
Silicon	ppm	● 3	---	---	---
Sodium	ppm	● 4	---	---	---
Potassium	ppm	● <1	---	---	---



Wear Metals

Iron	ppm	● 54	---	---	---
Copper	ppm	● <1	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● 1	---	---	---
Vanadium	ppm	0	---	---	---



Additives

Calcium	ppm	18	---	---	---
Magnesium	ppm	● 2	---	---	---
Zinc	ppm	13	---	---	---
Phosphorus	ppm	353	---	---	---
Barium	ppm	● <1	---	---	---
Boron	ppm	3	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL LS 80W90. Please confirm. All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
 Unique No: 5775087
 Signed: Kevin Marson
 Report Date: 10 May 2024



Graphs

