LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 113527-1216 - Rear Differential

Sample No: LH0290623

Oil Type: GEAR OIL SAE 80W90

_				
U Sam	ple Inforr	nation		
Sample Number		LH0290623	LH	
Sample Date		13 Jun 2024	13 Mar 2023	
Machine Hours		0	0	
Oil Hours		0	0	
Oil Changed		N/A	N/A	
Sample Status		NORMAL	NORMAL	
Varipic Otatus		NOTIVIAL	NOTHINAL	
Oil C	ondition			
Visc @ 40°C	cSt	178	O 176	
Cont	aminatio			
Water	%	NEG	NEG	
Silicon	ppm	0	O 1	
Sodium	ppm	2	4	
Potassium	ppm	0	O 0	
Wed	ır Metals			
Iron	ppm	12	O 17	
Copper	ppm	3	O 6	
Lead	ppm	0	O <1	
Tin	ppm	0	O 0	
Aluminum	ppm	0	O <1	
Chromium	ppm	0	O 0	
Molybdenum	ppm	0	O 0	
Nickel	ppm	0	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0	O <1	
Vanadium	ppm	0	0	
	itives			
Calcium	ppm	9	13	
Magnesium	ppm	0 <1	O <1	
Zinc	ppm	6	10	
D		0.00	0.000	

 \bigcirc <1

02



LIEBHERR CANADA LTEE 444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7

Contact: Martin Gagnon martin.gagnon@liebherr.com

T:

F: (418)276-9844

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LBADOLUnique No:5799607Signed:Wes DavisReport Date:14 Jun 2024

2257

0

() <1

ppm

ppm

Phosphorus

Barium

Boron

CONSTRUCTION EQUIPMENT





Graphs

