

LIEBHERR A944 038730-194 - Rear Differential

Sample No: LH0264403

.....


Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

LH0185258							
LI10103230							
29 Jan 2021							
27384							
0							
Changed							
NORMAL							
OIL CONDITION							
0 145							
	29 Jan 2021 27384 0 Changed NORMAL	29 Jan 2021 27384 0 Changed NORMAL	29 Jan 2021 27384 0 Changed NORMAL				

**				
	NTAMIN/	ATION		
Silicon	ppm	01	0 4	
Sodium	ppm	0	2	
Potassium	nnm	03		

Â				
WE/	AR META	LS		
Iron	ppm	0 18	123	
Copper	ppm	07	0 60	
Lead	ppm	○ <1	◯ <1	
Tin	ppm	0 ()	0	
Aluminum	ppm	0 (2	
Chromium	ppm	0 ()	0 1	
Molybdenum	ppm	○ <1	0	
Nickel	ppm	0 ()	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	○ <1	3	
Vanadium	ppm	0	0	







ALTER METAL

2080 SPINDT DR WAUPACA, WI US 54981 Contact: BRAD DORMADY brad.dormady@altertrading.com T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:	ALTWAUWI
Unique No:	10546779
Signed:	Angela Borella
Report Date:	07 Jul 2023







- -----

