LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L550 1756-58839 - Splitter Box

Sample No: LHMC160585

Oil Type: GEAR OIL SAE 90

SAMPLEINFORMATION						
Sample Number	LHMC160585					
Sample Date	19 Jul 2023					
Machine Hours	6327					
Oil Hours	2000					
Oil Changed	Changed					
Sample Status	NORMAL					

- Cup.o	Otatao								
OIL CONDITION									
Visc @		cSt	72.6						
-4									

CONTAMINATION								
Silicon	ppm	6						
Sodium	ppm	0						
Potassium	ppm	1						

WEAR METALS							
Iron	ppm	36					
Copper	ppm	0 1					
Lead	ppm	() <1					
Tin	ppm	0					
Aluminum	ppm	0					
Chromium	ppm	○ <1					
Molybdenum	ppm	3					
Nickel	ppm	2					
Titanium	ppm	0					
Silver	ppm	0					
Manganese	ppm	() <1					
Vanadium	ppm	0					

ADDITIVES							
Calcium	ppm	128					
Magnesium	ppm	6					
Zinc	ppm	50					
Phosphorus	ppm	323					
Barium	ppm	2					
Boron	ppm	18					



DREW TRANSPORT

2648 WEST 50TH STREET CHICAGO, IL US 60632

Contact: SERVICE MANAGER

T: (773)476-9472

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:DRECHIUnique No:10565974Signed:Don BaldridgeReport Date:25 Jul 2023

LIEBHERR







GRAPHS

