

ROADTEC RP190E 4130 - Left Auger

Sample No: LH0257954

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0257954	
Sample Date	25 Jul 2023	
Machine Hours	3460	
Oil Hours	0	
Oil Changed	Changed	
Sample Status	NORMAL	

107



OIL CONDITION

Visc @ 40°C

cSt

	NTAMINA	TION		
Silicon	ppm	<1	 	
Sodium	ppm	07	 	
Potassium	ppm	0 26	 	

Ä				
WEA	AR META	LS		
Iron	ppm	○ <1	 	
Copper	ppm	<1	 	
Lead	ppm	<1	 	
Tin	ppm	0	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	○ <1	 	
Nickel	ppm	0 (
Titanium	ppm	<1	 	
Silver	ppm	1	 	
Manganese	ppm	() <1	 	
Vanadium	ppm	1	 	



ADDITIVES

Calcium	ppm	○ <1	 	
Magnesium	ppm	0 12	 	
Zinc	ppm	0	 	
Phosphorus	ppm	0 24	 	
Barium	ppm	0	 	
Boron	ppm	0	 	





FINKBINER EQUIPMENT CO.

15 W 400 N FRONTAGE RD BURR RIDGE, IL US 60527 Contact: DON FITZGERALD dfitzgerald@finkbiner.com T: (815)546-8991 F: (630)654-3792

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:	LEC0033
Unique No:	10632190
Signed:	Don Baldridge
Report Date:	07 Sep 2023






Ferrous Alloys

GRAPHS

O



Non-ferrous Metals

