

LIEBHERR L550 1825-67138 - Front Differential

Sample No: LH0262930

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0262930	 	
Sample Date	27 Aug 2023	 	
Machine Hours	2391	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	ABNORMAL	 	

OIL

OIL CONDITION

Visc @ 40°C

-

-

cSt 🔘 183

Silicon	ppm	O 15				
Sodium	ppm	03				
Potassium	ppm	○ <1				

	R META	LS		
Iron	ppm	130	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	0 🔘	 	
Tin	ppm	08	 	
Aluminum	ppm	 <1	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	0 🔘	 	
Nickel	ppm	02	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	8 🔘	 	
Vanadium	maa	0	 	



ADDITIVES

Calcium	ppm	3	 	
Magnesium	ppm	0	 	
Zinc	ppm	0 18	 	
Phosphorus	ppm	0 2422	 	
Barium	ppm	0	 	
Boron	ppm	0	 	





O'NEIL CONSTRUCTION R.R. #1 BOBCAYGON, ON

CA KOM 1A0 Contact: WM O'NEIL

T: (705)738-3687 F: (705)738-5531

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:OUnique No:10Signed:DoReport Date:21

ONEBOB 10701187 Don Baldridge 21 Oct 2023

Submitted By: ?





GRAPHS

 \odot



Report Id: ONEBOB [WUSCAR] 05983892 (Generated: 10/22/2023 13:29:15) Rev: 1