


LIEBHERR R938 050886-1650 - Swing Drive

Sample No: LH0258264

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0258264	LH0258964	LH0243980	
Sample Date	08 Oct 2023	09 Aug 2023	31 Jan 2023	
Machine Hours	431	1993	575	
Oil Hours	0	1993	575	
Oil Changed	Not Changd	Changed	Changed	
Sample Status	NORMAL	ABNORMAL	NORMAL	



	ITAMINA	TION			
Water	%	NEG	0.722	NEG	
Silicon	ppm	0 9	0 6	0 4	
Sodium	ppm	06	2	03	
Potassium	ppm	0 15	0	02	

Ä					
WEA WEA	R METALS	5			
Iron	ppm	0 69	0 1364	697	
Copper	ppm	○ <1	0	◯ <1	
Lead	ppm	0 🔘	0	◯ <1	
Tin	ppm	0 ()	0	0	
Aluminum	ppm	0 🔘	◯ <1	0 1	
Chromium	ppm	01	0 20	0 10	
Molybdenum	ppm	0 🔘	0	◯ <1	
Nickel	ppm	0 🔘	○ <1	0	
Titanium	ppm	0	<1	<1	
Silver	ppm	0	0	0	
Manganese	ppm	01	0 13	8 🔘	
Vanadium	ppm	<1	0	0	

0 **ADDITIVES** Calcium 0 11 ppm 0 42 0 10 03 Magnesium 0 04 ppm 0 32 Zinc 0 25 16 ppm 0 1962 Phosphorus ppm 0 1569 0 1317 Barium 05 04 ppm 02 Boron ○ <1 ppm 0 1





M&F CONCRETE PRODUCTS CO 4002 CATLETT RD CATLETT, VA US 20119 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	MECCAT
Unique No:	10778745
Signed:	Don Baldridge
Report Date:	11 Dec 2023

Contact/Location: Service Manager - MECCAT





GRAPHS



Report Id: MECCAT [WUSCAR] 06028954 (Generated: 12/15/2023 09:18:56) Rev: 1