

LIEBHERR A934C 045480-1007 - Rear Right Wheel Hub

Sample No: LH0263944

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number		LH0263944	LHMC142264	LHMC106327			
Sample Date		19 Dec 2023	03 May 2019	02 Jun 2017			
Machine Hours		31068	22895	17931			
Oil Hours		2000	500	500			
Oil Changed		Changed	Changed	Changed			
Sample Status		NORMAL	NORMAL	NORMAL			
Visc @ 40°C	cSt	0 117	329	295.8			

Water	%	NEG	NEG	NEG		
Silicon	ppm	03	03	○ 5		
Sodium	ppm	0 2	01	2		
Potassium	ppm	0	08	01		

Õ					
WEA WEA	R META	LS			
Iron	ppm	0 29	9	6	
Copper	ppm	0 16	0 2	02	
Lead	ppm	0	◯ <1	0	
Tin	ppm	◯ <1	0	0	
Aluminum	ppm	○ <1	◯ <1	0 1	
Chromium	ppm	0	◯ <1	◯ <1	
Molybdenum	ppm	0 2	2	01	
Nickel	ppm	0	0	0	
Titanium	ppm	<1	<1	3	
Silver	ppm	0	0	0	
Manganese	ppm	() <1	◯ <1	◯ <1	
Vanadium	ppm	<1	0	0	

ADDITIVES					
Calcium	ppm	118	50	0 115	
Magnesium	ppm	0 21	03	○ 5	
Zinc	ppm	073	20	61	
Phosphorus	ppm	0 1252	947	843	
Barium	ppm	0	0	0	
Boron	ppm	0 172	0 154	0 148	





NORTHERN METAL RECYCLING

2800 PACIFIC ST N MINNEAPOLIS, MN US 55411 Contact: CHRIS GILMER chris.gilmer@emrgroup.com T: (612)305-7338 F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:NORMINLHUnique No:10844606Signed:Wes DavisReport Date:23 Jan 2024





Ô

GRAPHS

