LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH110 1227-155752 - Rear Differential

Sample No: LH0280582

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION							
Sample Number	LH0280582	LH0280571	LH0280560				
Sample Date	19 Mar 2024	20 Feb 2024	11 Jan 2024				
Machine Hours	1544	1022	507				
Oil Hours	0	0	0				
Oil Changed	Not Changd	Changed	Not Changd				
Sample Status	ATTENTION	NORMAL	NORMAL				

OILCO	NDITION				
Visc @ 40°C	cSt	103	O 149	149	

CONTAMINATION							
Water	%	NEG	NEG	NEG			
Silicon	ppm	4	8	7			
Sodium	ppm	1	O 2	4			
Potassium	ppm	0 <1	0	1			

WEAR METALS						
Iron	ppm	38	O 61	○ 34		
Copper	ppm	10	O 27	16		
Lead	ppm	0	O <1	O 0		
Tin	ppm	1	O 0	O <1		
Aluminum	ppm	() <1	O <1	O <1		
Chromium	ppm	() <1	O <1	O 0		
Molybdenum	ppm	2	O <1	0		
Nickel	ppm	0 <1	O 0	O <1		
Titanium	ppm	0	0	0		
Silver	ppm	0	0	0		
Manganese	ppm	() <1	O 2	1		
Vanadium	ppm	<1	<1	0		

ADDITIVES							
Calcium	ppm	172	110	106			
Magnesium	ppm	3	0	2			
Zinc	ppm	90	O 23	23			
Phosphorus	ppm	467	O 1459	1225			
Barium	ppm	0	O <1	2			
Boron	ppm	2	O 6	5			



KINDER MORGAN 4301 IVERSON TRINITY, AL US 35601

Contact: CHIP OAKES

T: (256)350-0006 F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The condition of the oil is acceptable for the time in service.

Depot: KINTRI
Unique No: 10950660
Signed: Don Baldridge
Report Date: 01 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

