

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH80M 1218-157090 - Rear Differential

Sample No: LH0282893

Oil Type: GEAR OIL SAE 80W90



KINDER MORGAN

4301 IVERSON

TRINITY, AL

US 35601

Contact: RICKY JOHNSON

ricky_johnson@kindermorgan.com

T:

F: (256)355-5250



SAMPLE INFORMATION

Sample Number	LH0282893	---	---	---
Sample Date	19 Mar 2024	---	---	---
Machine Hours	545	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 139	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 10	---	---	---
Sodium	ppm	● 4	---	---	---
Potassium	ppm	● <1	---	---	---



WEAR METALS

Iron	ppm	● 33	---	---	---
Copper	ppm	● 11	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 2	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● 1	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● 1	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	● 186	---	---	---
Magnesium	ppm	● <1	---	---	---
Zinc	ppm	● 34	---	---	---
Phosphorus	ppm	● 1503	---	---	---
Barium	ppm	● 0	---	---	---
Boron	ppm	● 6	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINTRI

Unique No: 10950668

Signed: Wes Davis

Report Date: 28 Mar 2024



GRAPHS

