

LIEBHERR R945 058083-1866 - Splitter Box

Sample No: LH0278790

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON

0 195

Numéro d'échant.	LH0278790	 	
Date d'échant.	29 Jan 2024	 	
Heures de la Machine	444	 	
Heures de l'huile	0	 	
Huile changée	Changed	 	
Statut de l'echant.	NORMAL	 	

ÉTAT D'HUILE

Visc 40°C

cSt

11				
Eau	%	NEG		
Silicium	ppm	01		
Sodium	ppm	02		
Potassium	ppm	02		

Ä				
₩ MéT	AUX D'U	ISURE		
Fer	ppm	21	 	
Cuivre	ppm	○ <1	 	
Plomb	ppm	○ <1	 	
Étain	ppm	0 ()	 	
Aluminium	ppm	○ <1	 	
Chrome	ppm	0 ()	 	
Molybdène	ppm	0 ()	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	○ <1	 	
Vanadium	ppm	0	 	

0 **ADDITIFS** Calcium 0 10 ppm Magnésium 02 ppm Zinc 0 12 ppm Phosphore ppm 0 1413 Baryum 0 ppm Bore ppm ○ <1





GERDAU AMERISTEEL

2025 RIVER RD. LONDON, ON CA N5W 6C4 Contact: Scott MacDonald

T: (519)455-4639 F: (519)451-3623

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:**


GER202LON 5721319 Wes Davis 30 Jan 2024





GRAPHS

 \odot



ID du rapport: GER202LON [WCAMIS] 02612224 (Generated: 02/02/2024 11:14:55) Rev: 1