

## LIEBHERR A922146822-1509 - Front Right Wheel Hub

Sample No: LH0285071

Oil Type: GEAR OIL SAE 80W90

/is

## **INFORMATION SUR L'ÉCHANTILLON**

Numéro d'échant.	LH0285071	 	
Date d'échant.	29 Jan 2024	 	
Heures de la Machine	1252	 	
Heures de l'huile	0	 	
Huile changée	Changed	 	
Statut de l'echant.	NORMAL	 	

) ÉTATI	D'HUILE				
sc 40°C	cSt	0 139			

	ramin/	TION		
Eau	%	NEG	 	
Silicium	ppm	04	 	
Sodium	ppm	04	 	
Potassium	ppm	01	 	

Ä				
MéT	AUX D'U	ISURE		
Fer	ppm	0 13	 	
Cuivre	ppm	<b>16</b>	 	
Plomb	ppm	<b>○</b> <1	 	
Étain	ppm	0	 	
Aluminium	ppm	<b>○</b> <1	 	
Chrome	ppm	<b>○</b> <1	 	
Molybdène	ppm	0	 	
Nickel	ppm	<b>○</b> <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	01	 	
Vanadium	ppm	0	 	

0 **ADDITIFS** Calcium ppm 09 Magnésium 01 ppm Zinc 0 19 ppm Phosphore ppm 0 1653 Baryum 0 16 ppm Bore ppm 0 128





PNR RAILWORKS INC. 65 MASSEY ROAD GUELPH NW, ON CA N1H 7M6

CA N1H 7M6 Contact: Service Manager

T: F:

## Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date:


PNRGUE 5721330 Wes Davis 30 Jan 2024





GRAPHS

 $\odot$ 



ID du rapport: PNRGUE [WCAMIS] 02612235 (Generated: 02/02/2024 11:16:15) Rev: 1