

LIEBHERR A922146822-1509 - Rear Left Wheel Hub

Sample No: LH0285070

Oil Type: GEAR OIL SAE 80W90

A

INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0285070	 	
Date d'échant.	29 Jan 2024	 	
Heures de la Machine	1252	 	
Heures de l'huile	0	 	
Huile changée	Changed	 	
Statut de l'echant.	NORMAL	 	

🌒 ÉTATI	D'HUILE			
isc 40°C	cSt	0 138	 	

	ITAMIN/	ATION		
Eau	%	NEG	 	
Silicium	ppm	08	 	
Sodium	ppm	07	 	
Potassium	ppm	0 2	 	

Ä				
Mél	I'AUX D'L	JSURE		
Fer	ppm	180	 	
Cuivre	ppm	0 16	 	
Plomb	ppm	◯ <1	 	
Étain	ppm	0	 	
Aluminium	ppm	● 4	 	
Chrome	ppm	02	 	
Molybdène	ppm	0	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	05	 	
Vanadium	ppm	0	 	

٥ **ADDITIFS** Calcium 0 16 ppm Magnésium ppm 02 Zinc 0 28 ppm Phosphore ppm 0 1652 Baryum 0 19 ppm Bore ppm 0 97





PNR RAILWORKS INC. 65 MASSEY ROAD GUELPH NW, ON CA. N1H 7M6

GUELPH NW, ON CA N1H 7M6 Contact: Service Manager

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date:


PNRGUE 5721339 Wes Davis 30 Jan 2024





GRAPHS

 \odot



ID du rapport: PNRGUE [WCAMIS] 02612244 (Generated: 02/02/2024 11:16:36) Rev: 1