

LIEBHERR LH40M 146402-1215 - Splitter Box

Sample No: LH0285165

Oil Type:

GEAR OIL SAE 75W90

on type.

Visc 40°C

	MATION	SUR L'ÉCHAN	TILLON
Numéro d'échant.		LH0285165	LH0266028
Date d'échant.		08 Feb 2024	27 Jul 2023

981

Changed

NORMAL

0



TAT D'HUILE				
	cSt	0 108		

**				
	ITAMINA	TION		
Eau	%	NEG	NEG	
Silicium	ppm	<mark></mark> <1	0 2	
Sodium	ppm	01	03	
Potassium	ppm	01	0 2	

511

Changed

NORMAL

199

0

A				
Mé	raux d'u	JSURE		
Fer	ppm	0 15	24	
Cuivre	ppm	() <1	01	
Plomb	ppm	() <1	0	
Étain	ppm	0	0 0	
Aluminium	ppm	○ <1	◯ <1	
Chrome	ppm	0	○ <1	
Molybdène	ppm	0	0	
Nickel	ppm	○ <1	0	
Titane	ppm	0	0	
Argent	ppm	0	0	
Manganèse	ppm	○ <1	2	
Vanadium	ppm	0	0	

ø **ADDITIFS** Calcium ppm 05 0 11 Magnésium 01 $\bigcirc 3$ ppm 0 24 Zinc 013 ppm Phosphore ppm 0 1032 0 1705 Baryum 0 ppm ○ <1 Bore 02 ppm 02





JOSEPH & COMPANY INC 257 VICTORIA ST N KITCHENER, ON CA N2H 5C9 Contact: Service Manager

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:JUnique No:5Signed:VReport Date:1


JOS257KIT 5723822 Wes Davis 12 Feb 2024





GRAPHS

 \odot



ID du rapport: JOS257KIT [WCAMIS] 02614727 (Generated: 02/14/2024 14:29:10) Rev: 1