LIEBHERR

INFORMATION SUR L'ÉCHANTILLON

CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 146402-1215 - Front Differential

Sample No: LH0285162

Argent

Manganèse

Vanadium

Calcium

Zinc


Bore

Magnésium

Phosphore

Baryum

Oil Type: GEAR OIL SAE 80W90





JOSEPH & COMPANY INC 257 VICTORIA ST N KITCHENER, ON CA N2H 5C9

Contact: Service Manager

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:JOS257KITUnique No:5723910Signed:Wes DavisReport Date:13 Feb 2024

0

0

6

0 <1

10

94

101

1601

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIFS

LIEBHERR







GRAPHS

