LIEBHERR



LIEBHERR LH50M 149704-1216 - Rear Right Wheel Hub

Sample No: LH0286747

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON						
Numéro d'échant.	LH0286747					
Date d'échant.	18 Mar 2024					
Heures de la Machine	1366					
Heures de l'huile	0					
Huile changée	Changed					
Statut de l'echant.	NORMAL					

ÉTAT D'HUILE							
Visc 40°C	cSt	154					

CONTAMINATION							
Eau	%	NEG					
Silicium	ppm	11					
Sodium	ppm	3					
Potassium	ppm	1					

MéTAUX D'USURE						
Fer	ppm	40				
Cuivre	ppm	26				
Plomb	ppm	() <1				
Étain	ppm	0				
Aluminium	ppm	1				
Chrome	ppm	○ <1				
Molybdène	ppm	0				
Nickel	ppm	○ <1				
Titane	ppm	0				
Argent	ppm	0				
Manganèse	ppm	1				
Vanadium	ppm	0				

ADDITIFS							
Calcium	ppm	18					
Magnésium	ppm	0 <1					
Zinc	ppm	26					
Phosphore	ppm	1402					
Baryum	ppm	1					
Bore	ppm	7					



DUNDEE RECYCLING LTD 1092 BRIDGE ST NEW DUNDEE (WILMOT), ON CA N0B 2E0 Contact: SERVICE

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: DUNWIL
Unique No: 5748247
Signed: Wes Davis
Report Date: 19 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

