LIEBHERR



LIEBHERR LH50M 149704-1216 - Rear Left Wheel Hub

Sample No: LH0286748

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON						
Numéro d'échant.	LH0286748					
Date d'échant.	18 Mar 2024					
Heures de la Machine	1366					
Heures de l'huile	0					
Huile changée	Changed					
Statut de l'echant.	NORMAL					

A							
ETATI)'HUILE						
Visc 40°C	cSt	153					

CONTAMINATION							
Eau	%	NEG					
Silicium	ppm	11					
Sodium	ppm	3					
Potassium	ppm	2					

MéTAUX D'USURE						
Fer	ppm	41				
Cuivre	ppm	26				
Plomb	ppm	() <1				
Étain	ppm	0				
Aluminium	ppm	1				
Chrome	ppm	() <1				
Molybdène	ppm	0				
Nickel	ppm	○ <1				
Titane	ppm	0				
Argent	ppm	0				
Manganèse	ppm	1				
Vanadium	ppm	0				

ADDI	TIFS			
Calcium	ppm	17	 	
Magnésium	ppm	0 <1	 	
Zinc	ppm	25	 	
Phosphore	ppm	1407	 	
Baryum	ppm	0 <1	 	
Bore	ppm	6	 	



DUNDEE RECYCLING LTD 1092 BRIDGE ST NEW DUNDEE (WILMOT), ON CA N0B 2E0 Contact: SERVICE

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:DUNWILUnique No:5748250Signed:Wes DavisReport Date:19 Mar 2024







GRAPHS

