LIEBHERR



LIEBHERR LH50M 149704-1216 - Front Left Wheel Hub

Sample No: LH0286746

Oil Type: GEAR OIL SAE 80W90

INFORMATION SUR L'ÉCHANTILLON					
Numéro d'échant.	LH0286746				
Date d'échant.	18 Mar 2024				
Heures de la Machine	1366				
Heures de l'huile	0				
Huile changée	Changed				
Statut de l'echant.	NORMAL				
ÉTATBULUE					

CONTAMINATION						
Eau	%	NEG				
Silicium	ppm	3				
Sodium	ppm	4				
Potassium	ppm	() <1				

₩ Mé1	TAUX D'U	SURE		
Fer	ppm	o 5	 	
Cuivre	ppm	18	 	
Plomb	ppm	○ <1	 	
Étain	ppm	0	 	
Aluminium	ppm	○ <1	 	
Chrome	ppm	0	 	
Molybdène	ppm	0	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	0	 	
Vanadium	ppm	0	 	

variaululli	ppiii	U				
ADDITIFS						
Calcium	ppm	5				
Magnésium	ppm	1				
Zinc	ppm	15				
Phosphore	ppm	1802				
Baryum	ppm	4				
Bore	ppm	140				



DUNDEE RECYCLING LTD 1092 BRIDGE ST NEW DUNDEE (WILMOT), ON CA N0B 2E0 Contact: SERVICE

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:DUNWILUnique No:5748251Signed:Wes DavisReport Date:19 Mar 2024





GRAPHS

