LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 077508 - Rear Right Wheel Hub

Sample No: LH0289765

Oil Type: GEAR OIL SAE 75W90

_					
Information sur l'échantillon					
Numéro d'échant.	LH0289765				
Date d'échant.	01 May 2024				
Heures de la Machine	16364				
Heures de l'huile	0				
Huile changée	N/A				
Statut de l'echant.	NORMAL				

Otatat ao i oonanti				
État d	'huile			
Visc 40°C	cSt	91.5	 	
_				

Cont	amination	ı		
Eau	%	NEG	 	
Silicium	ppm	3	 	
Sodium	ppm	2	 	
Potassium	ppm	() <1	 	

Métaux d'usure					
Fer	ppm	52			
Cuivre	ppm	5			
Plomb	ppm	0			
Étain	ppm	0			
Aluminium	ppm	 <1			
Chrome	ppm	0			
Molybdène	ppm	0			
Nickel	ppm	0			
Titane	ppm	0			
Argent	ppm	0			
Manganèse	ppm	○ <1			
Vanadium	ppm	0			

Addi	tifs			
Calcium	ppm	20	 	
Magnésium	ppm	22	 	
Zinc	ppm	41	 	
Phosphore	ppm	1115	 	
Baryum	ppm	0	 	
Bore	ppm	169	 	



J.M. BASTILLE ACIER INC 396 RUE TEMISCOUATA,, CP 744 RIVIERE DU LOUP, QC CA G5R 3Z3

Contact: MANAGER SERVICE

T: (418)862-3346 F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: JMBRIV
Unique No: 5776161
Signed: Wes Davis
Report Date: 13 May 2024

LIEBHERR







Graphs

