LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 077508 - Rear Differential

Sample No: LH

Oil Type: GEAR OIL SAE 75W90

Information sur l'échantillon						
Numéro d'échant.	LH					
Date d'échant.	01 May 2024					
Heures de la Machine	16364					
Heures de l'huile	0					
Huile changée	N/A					
Statut de l'echant.	NORMAL					

otatat ao i conant.		HOILINAL		
État d'	huile			
Visc 40°C	cSt	91.3	 	
_				

Cont	amination				
Eau	%	NEG			
Silicium	ppm	3	***	***	
Sodium	ppm	2			
Potassium	ppm	1		***	

	○ 57			
	57			
	~			
pm	5			
ppm	0			
ppm	0			
pm	0 <1			
ppm	0			
ppm	0			
ppm	0			
pm	0			
pm	0			
pm	0 <1			
pm	0			
	om o	om	5 cm	5 om

Additifs						
Calcium	ppm	20				
Magnésium	ppm	24				
Zinc	ppm	43				
Phosphore	ppm	1145				
Baryum	ppm	0				
Bore	ppm	178				



J.M. BASTILLE ACIER INC 396 RUE TEMISCOUATA,, CP 744 RIVIERE DU LOUP, QC CA G5R 3Z3

Contact: MANAGER SERVICE

T: (418)862-3346 F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: JMBRIV
Unique No: 5776167
Signed: Wes Davis
Report Date: 13 May 2024

Submitted By: Olivier Galimi

LIEBHERR







Graphs

