CONSTRUCTION EQUIPMENT





LIEBHERR L550 076577-1825 - Front Right Wheel Hub

Sample No: LH0290656

_

Oil Type: **GEAR OIL SAE 80W90**

Infor	mation	sur l'échantillo	n	
Numéro d'échant.		LH0290656		
Date d'échant.		11 Jun 2024		
Heures de la Machine)	541		
Heures de l'huile		0		
Huile changée		N/A		
Statut de l'echant.		NORMAL		
Étato	l'huile			
Visc 40°C	cSt	194		

**							
Conto	Contamination						
Eau	%	NEG					
Silicium	ppm	29					
Sodium	ppm	6					
Potassium	ppm	0					
10) as 48 Almanna							

Méte	aux d'usu	re		
Fer	ppm	264	 	
Cuivre	ppm	79	 	
Plomb	ppm	2	 	
Étain	ppm	7	 	
Aluminium	ppm	2	 	
Chrome	ppm	2	 	
Molybdène	ppm	0	 	
Nickel	ppm	4	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	20	 	
Vanadium	ppm	0	 	

itifs				
ppm	8			
ppm	5			
ppm	23			
ppm	2209			
ppm	() <1			
ppm	3			
	ppm ppm ppm ppm	ppm	ppm	ppm



142975 CANADA LTEE (MIRONOR)

751 CH DE LA 2E CONCESSION BROWNSBURG-CHATHAM, QC

CA J8G 1S9

Contact: Francis Sylvestre

T: (450)898-9225

F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: 142BRO Unique No: 5799615 Signed: Kevin Marson **Report Date:** 17 Jun 2024

LIEBHERR







Graphs

