LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR TA230 142551-1513 - Rear Axle

Sample No: LH0290738

Oil Type: LIEBHERR GEAR MF 80W

Information sur l'échantillon						
Numéro d'échant.	LH0290738					
Date d'échant.	27 Jun 2024					
Heures de la Machine	2065					
Heures de l'huile	0					
Huile changée	N/A					
Statut de l'echant.	NORMAL					

Etat d	'huile			
Visc 40°C	cSt	61.9	 	

Conte	amination	ı		
Eau	%	NEG	 	
Silicium	ppm	15	 	
Sodium	ppm	21	 	
Potassium	ppm	0 <1	 	
- Marie				

Métaux d'usure						
ppm	278					
ppm	169					
ppm	4					
ppm	9					
ppm	5					
ppm	2					
ppm	0					
ppm	5					
ppm	<1					
ppm	<1					
ppm	55					
ppm	0					
	ppm	ppm	ppm 278 ppm 169 ppm 4 ppm 9 ppm 5 ppm 0 ppm 5 ppm <1	ppm 278 ppm 169 ppm 4 ppm 9 ppm 5 ppm 0 ppm 5 ppm <1		

vanadium	ppm	0					
Additifs							
Calcium	ppm	3288					
Magnésium	ppm	11					
Zinc	ppm	1395					
Phosphore	ppm	1222					
Baryum	ppm	1					
Bore	ppm	96					



LES ENTREPRISES LOU-VIL INC

255 BOUL. LOUIS XIV QUEBEC, QC CA G2K 1W6

Contact: Service Manager

T: (418)622-2958

F:

Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:LOUQUEUnique No:5812692Signed:Kevin MarsonReport Date:11 Jul 2024







Graphs

