


OIL ANALYSIS REPORT



Haul Truck HT5023

Component **Diesel Engine**

DIESEL ENGINE OIL SAE 15W40 (--- LTR)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 15W40. Please confirm.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

AE 15W40 (L	-TR)			Jun 2023		
SAMPLE INFOR	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		PC0050695		
Sample Date		Client Info		04 Jun 2023		
Machine Age	hrs	Client Info		9532		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINAT	ION	method	limit/base	current	history 1	history 2
-uel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	_S	method	limit/base	current	history 1	history 2
ron	ppm	ASTM D5185(m)	>100	38		
Chromium	ppm	ASTM D5185(m)	>20	<1		
Nickel	ppm	ASTM D5185(m)	>4	0		
Γitanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)	>3	0		
Aluminum	ppm	ASTM D5185(m)	>20	1		
_ead	ppm	ASTM D5185(m)	>40	9		
Copper	ppm	ASTM D5185(m)	>330	2		
Γin	ppm	ASTM D5185(m)	>15	<1		
Antimony	ppm	ASTM D5185(m)		0		
/anadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185(m)	250	1		
Barium	ppm	ASTM D5185(m)	10	0		
Molybdenum	ppm	ASTM D5185(m)	100	63		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)	450	1037		
Calcium	ppm	ASTM D5185(m)	3000	1117		
Phosphorus	ppm	ASTM D5185(m)	1150	1076		
Zinc	ppm	ASTM D5185(m)	1350	1231		
Sulfur	ppm	ASTM D5185(m)	4250	2477		
₋ithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	NTS	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185(m)	>25	4		
Sodium	ppm	ASTM D5185(m)	>158	2		
Potassium	ppm	ASTM D5185(m)	>20	<1		
INFRA-RED		method	limit/base	current	history 1	history 2
Soot %	%	ASTM D7844*	>3	2.1		
Vitration	Abs/cm	ASTM D7624*	>20	9.0		
Sulfation	Abs/.1mm	ASTM D7415*	>30	23.8		
FLUID DEGRA	DATION	method	limit/base	current	history 1	history 2
Oxidation	Abs/.1mm	ASTM D7414*	>25	16.0		



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0050695 : 02567677

Received Diagnosed : 5604723 Diagnostician

: 04 Jul 2023

: 04 Jul 2023

: Wes Davis

Test Package : MOB 1 (Additional Tests: KV40, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Lakeshore Gold Timmins West

Timmins, ON CA Contact: Adam Koscielak

adam.koscielak@HFSinclair.com

T: F: