


OIL ANALYSIS REPORT

WL0416 Component

Diesel Engine

CASE 10W40 MAT 3571 (-





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

l (GAL)				Jun2023		
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0088311		
Sample Date		Client Info		15 Jun 2023		
Machine Age	hrs	Client Info		5944		
Oil Age	hrs	Client Info		500		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINAT	TION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
					•	
ron	ppm	ASTM D5185(m)	>100	11		
Chromium	ppm	ASTM D5185(m)	>20	<1		
Nickel	ppm	ASTM D5185(m)	>4	0		
Fitanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>3	<1		
Aluminum	ppm	ASTM D5185(m)	>20	4		
_ead	ppm	ASTM D5185(m)	>40	<1		
Copper	ppm	ASTM D5185(m)	>330	4		
īin	ppm	ASTM D5185(m)	>15	0		
Antimony	ppm	ASTM D5185(m)		2		
/anadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		56		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		19		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)		153		
Calcium	ppm	ASTM D5185(m)		2153		
Phosphorus	ppm	ASTM D5185(m)		1090		
Zinc	ppm	ASTM D5185(m)		1224		
Sulfur	ppm	ASTM D5185(m)		3194		
₋ithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	8		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	<1		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0		
Nitration	Abs/cm	ASTM D7624*	>20	10.6		
Sulfation	Abs/.1mm	ASTM D7415*	>30	23.1		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	18.2		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5616709 Test Package : MOB 1

: GFL0088311 : 02571658

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received Diagnosed Diagnostician : Wes Davis

: 24 Jul 2023 : 24 Jul 2023

GFL Environmental - Boylston 151 Waste Management Road Hiwy 16

Boylston, NS CA B0H 1G0 Contact: Bruce Avery bruce.avery@gflenv.com T:

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

F: Contact/Location: Bruce Avery - GFL968