

OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Machine Id 165171 DRIVE

Component

Gearbox

PETRO CANADA TURBOFLO R&O 220 (---

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

CAL						
GAL)				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0070422		
Sample Date		Client Info		08 Aug 2023		
Machine Age	mths	Client Info		0		
Oil Age	mths	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METALS	3	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
ron	ppm	ASTM D5185(m)	>200	<1		
Chromium	ppm	ASTM D5185(m)	>15	0		
Nickel	ppm	ASTM D5185(m)	>15	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
_ead	ppm	ASTM D5185(m)	>100	0		
Copper	ppm	ASTM D5185(m)	>200	0		
Γin	ppm	ASTM D5185(m)	>25	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
/anadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		0		
Calcium	ppm	ASTM D5185(m)	0	<1		
Phosphorus	ppm	ASTM D5185(m)	4	9		
Zinc	ppm	ASTM D5185(m)		3		
Sulfur	ppm	ASTM D5185(m)	J	1036		
_ithium	ppm	ASTM D5185(m)		<1		
		method	limit/base	current	history1	history2
						— Historyz
Silicon	ppm	ASTM D5185(m)	>50	<1		
Sodium	ppm	ASTM D5185(m)	00	0		
Potassium	ppm	ASTM D5185(m)	>20	<1		
FLUID DEGRAD	ATION	method				history2


Acid Number (AN)

mg KOH/g ASTM D974* 0.17

0.11



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: PC0070422

: 02576566 : 5629626

Received Diagnosed Diagnostician

: 17 Aug 2023 : 21 Aug 2023

: Wes Davis

Test Package : IND 2 (Additional Tests: KV100, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Dryden Fibre

Box 3001, 1 Duke Street Dryden, ON **CA P8N 2Z7**

Contact: Yvon St. Laurent yvon.stlaurent@domtar.com

T: (807)223-9838 F: (807)223-9176