


## **PROBLEM SUMMARY**

**Gas Compression [450210547]** 

Methanol Wellhead Injection Pump D (S/N Sample Tag PD-42010D)

**Unknown Component** 

**NOT GIVEN (120 LTR)** 





### **COMPONENT CONDITION SUMMARY**



#### RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample. Please provide more complete information on your next sample.

PROBLEMATIC TEST RESULTS									
Sample Status		SEVERE							
Particles >4µm	ASTM D7647 >5	<b>88605</b>							
Particles >6µm	ASTM D7647 >	<b>30824</b>							
Particles >14µm	ASTM D7647 >	160 <b>4 900</b>							
Particles >21µm	ASTM D7647 >4	<b>40 A8</b>							
Oil Cleanliness	ISO 4406 (c) >1	9/17/14 <b>  24/22/17</b>							

**Customer Id: TERHAM** Sample No.: PC Lab Number: 02590284

Test Package: MAR 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Information Required			?	Please specify the brand, type, and viscosity of the oil on your next sample. Please provide more complete information on your next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

# HISTORICAL DIAGNOSIS




## **OIL ANALYSIS REPORT**

# **Gas Compression [450210547]**

Methanol Wellhead Injection Pump D (S/N Sample Tag PD-42010D)

**Unknown Component** 

**NOT GIVEN (120 LTR)** 





### **DIAGNOSIS**

#### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample. Please provide more complete information on your next sample.

#### Wear

All component wear rates are normal.

### Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the sample.


#### **Fluid Condition**

The AN level is acceptable for this fluid. The sample is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		-		Dct2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC		
Sample Date		Client Info		05 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)		3		
Chromium	ppm	ASTM D5185(m)		0		
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)		0		
Lead	ppm	ASTM D5185(m)		0		
Copper	ppm	ASTM D5185(m)		<1		
Tin	ppm	ASTM D5185(m)		0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
ADDITIVES	nnm		limit/base		history1	history2
Boron	ppm	ASTM D5185(m)	limit/base	2	•	•
Boron Barium	ppm	ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1		
Boron Barium Molybdenum	ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1 0		
Boron Barium Molybdenum Manganese	ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1 0		
Boron Barium Molybdenum Manganese Magnesium	ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1 0 0		
Boron Barium Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1 0 0 0 0		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 <1 0 0 0 0 <1 83		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc	ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 <1 0 0 0 0 <1 83 <1		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 <1 0 0 0 0 <1 83 <1 1994		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)		2 <1 0 0 0 <1 83 <1 1994		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 <1 0 0 0 0 <1 83 <1 1994 <1 current		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)		2 <1 0 0 0 0 <1 83 <1 1994 <1 current 0		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 <1 0 0 0 0 <1 83 <1 1994 <1 current 0 <1		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2		history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium FLUID CLEANI	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	limit/base	2 <1 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 current		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium FLUID CLEANI Particles >4µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m) ASTM D5185(m)	limit/base >20 limit/base >5000	2 <1 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 <ul> <li>current</li> <li>88605</li> </ul>		history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium FLUID CLEANI Particles >4µm Particles >6µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m) ASTM D5185(m)	limit/base >20 limit/base >5000 >1300	2 <1 0 0 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 0 current \$8605 \$30824	history1 history1	
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINAN Silicon Sodium Potassium  FLUID CLEANI Particles >4µm Particles >14µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m) ASTM D7647 ASTM D7647	limit/base >20 limit/base >5000 >1300 >160	2 <1 0 0 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 current \$88605 30824 900		history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINAN Silicon Sodium Potassium Particles >4µm Particles >14µm Particles >21µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	limit/base >20 limit/base >5000 >1300 >160 >40	2 <1 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 current    88605 30824  900  88	history1 history1	history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINAN Silicon Sodium Potassium Particles >4µm Particles >14µm Particles >21µm Particles >38µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m)  ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	limit/base >20 limit/base >5000 >1300 >160 >40 >10	2 <1 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 current  \$8605 30824 \$900 \$88 1		history2 history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINAN Silicon Sodium Potassium Particles >4µm Particles >14µm Particles >21µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D7647 ASTM D7647 ASTM D7647 ASTM D7647	limit/base >20 limit/base >5000 >1300 >160 >40	2 <1 0 0 0 <1 83 <1 1994 <1 current 0 <1 0 current    88605 30824  900  88		history2 history2



### OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: PC

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 02590284 Diagnosed

: 5659350 Diagnostician : Kevin Marson

: 19 Oct 2023

: 20 Oct 2023

Test Package : MAR 2 (Additional Tests: KV100, PQ, PrtCount, TAN Man, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

**Suncor - Terra Nova Projects** Scotia Centre, 235 Water Strret

St. John's, NL CA A1C 1B6 Contact: Josh Hynes joshynes@suncor.com

T: (709)778-3575 F: (709)724-2835