


OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Machine Id
P145

Component
Diesel Engine

Fluid
PETRO CANADA DURON HP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			PC0083805	PC0067595	---
Sample Date	Client Info			16 Jan 2024	16 Nov 2022	---
Machine Age	kms	Client Info		140547	110371	---
Oil Age	kms	Client Info		0	0	---
Oil Changed	Client Info			Changed	Changed	---
Sample Status				NORMAL	NORMAL	---

CONTAMINATION		method	limit/base	current	history1	history2
Fuel	WC Method	>5		<1.0	<1.0	---
Water	WC Method	>0.2		NEG	NEG	---




WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	53	35	---
Chromium	ppm	ASTM D5185(m)	>20	3	1	---
Nickel	ppm	ASTM D5185(m)	>4	<1	<1	---
Titanium	ppm	ASTM D5185(m)		0	<1	---
Silver	ppm	ASTM D5185(m)	>3	<1	<1	---
Aluminum	ppm	ASTM D5185(m)	>20	14	3	---
Lead	ppm	ASTM D5185(m)	>40	<1	<1	---
Copper	ppm	ASTM D5185(m)	>330	6	14	---
Tin	ppm	ASTM D5185(m)	>15	0	<1	---
Antimony	ppm	ASTM D5185(m)		0	<1	---
Vanadium	ppm	ASTM D5185(m)		0	0	---
Beryllium	ppm	ASTM D5185(m)		0	0	---
Cadmium	ppm	ASTM D5185(m)		0	0	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	3	4	---
Barium	ppm	ASTM D5185(m)	0	0	0	---
Molybdenum	ppm	ASTM D5185(m)	60	63	61	---
Manganese	ppm	ASTM D5185(m)	0	<1	<1	---
Magnesium	ppm	ASTM D5185(m)	1010	969	996	---
Calcium	ppm	ASTM D5185(m)	1070	1087	1125	---
Phosphorus	ppm	ASTM D5185(m)	1150	982	1047	---
Zinc	ppm	ASTM D5185(m)	1270	1164	1214	---
Sulfur	ppm	ASTM D5185(m)	2060	2642	2446	---
Lithium	ppm	ASTM D5185(m)		<1	<1	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	8	11	---
Sodium	ppm	ASTM D5185(m)		28	6	---
Potassium	ppm	ASTM D5185(m)	>20	46	4	---
Glycol	%	ASTM D7922*		0.0	NEG	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	1	0.7	---
Nitration	Abs/cm	ASTM D7624*	>20	14.0	13.7	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	30.7	32.3	---

OIL ANALYSIS REPORT











FLUID DEGRADATION	method	limit/base	current	history1	history2	
Oxidation	Abs./1mm	ASTM D7414*	>25	31.6	33.5	---

VISUAL	method	limit/base	current	history1	history2	
Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	---
Free Water	scalar	Visual*		NEG	NEG	---

FLUID PROPERTIES	method	limit/base	current	history1	history2	
Visc @ 40°C	cSt	ASTM D7279(m)	118.2	114	110	---
Visc @ 100°C	cSt	ASTM D7279(m)	15.6	15.0	14.6	---
Viscosity Index (VI)	Scale	ASTM D2270*	139	136	136	---

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0083805 **Received** : 01 Mar 2024
Lab Number : **02619172** **Tested** : 01 Mar 2024
Unique Number : 5736282 **Diagnosed** : 01 Mar 2024 - Kevin Marson
Test Package : MOB 1 (Additional Tests: Glycol, KV40, VI)

TORONTO FIRE SERVICES
 40 TORYORK DRIVE
 TORONTO, ON
 CA M9L 1X6
 Contact: Antonio Rodrigues
 antonio.rodrigues@toronto.ca
 T:
 F: (416)338-9207

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.