




OIL ANALYSIS REPORT

Sample Rating Trend

VISCOSITY



Machine Id
911024
 Component
Diesel Engine
 Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)



DIAGNOSIS

Recommendation

Aucune mesure corrective n'est recommandée pour l'instant. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition.

Wear

Les taux d'usure de tous les composants sont normaux.

Contamination

La teneur en carburant est négligeable. Il n'y a aucun indice de contamination dans l'huile.

Fluid Condition

La viscosité de l'échantillon se situe dans la portée de l'SAE 30; nous vous conseillons de vérifier. L'état de l'huile est acceptable pour la durée de service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		GFL0107624	GFL0096343	GFL0088878
Sample Date	Client Info		25 Mar 2024	11 Oct 2023	12 Sep 2023
Machine Age	kms	Client Info	192031	171412	6995
Oil Age	kms	Client Info	0	600	600
Oil Changed	Client Info		Changed	Changed	Changed
Sample Status			ABNORMAL	NORMAL	NORMAL

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.2	NEG	NEG	NEG
Glycol	WC Method		NEG	NEG	NEG

WEAR METALS

	method	limit/base	current	history1	history2	
Iron	ppm	ASTM D5185(m)	>120	17	3	11
Chromium	ppm	ASTM D5185(m)	>20	<1	0	<1
Nickel	ppm	ASTM D5185(m)	>5	<1	0	<1
Titanium	ppm	ASTM D5185(m)	>2	0	0	0
Silver	ppm	ASTM D5185(m)	>2	0	<1	<1
Aluminum	ppm	ASTM D5185(m)	>20	2	<1	2
Lead	ppm	ASTM D5185(m)	>40	0	<1	<1
Copper	ppm	ASTM D5185(m)	>330	1	<1	2
Tin	ppm	ASTM D5185(m)	>15	<1	0	<1
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0

ADDITIVES

	method	limit/base	current	history1	history2	
Boron	ppm	ASTM D5185(m)	0	4	3	2
Barium	ppm	ASTM D5185(m)	0	0	<1	<1
Molybdenum	ppm	ASTM D5185(m)	60	59	54	70
Manganese	ppm	ASTM D5185(m)	0	0	0	0
Magnesium	ppm	ASTM D5185(m)	1010	929	890	1107
Calcium	ppm	ASTM D5185(m)	1070	1129	1025	1226
Phosphorus	ppm	ASTM D5185(m)	1150	939	917	1083
Zinc	ppm	ASTM D5185(m)	1270	1147	1099	1352
Sulfur	ppm	ASTM D5185(m)	2060	2158	2520	2677
Lithium	ppm	ASTM D5185(m)		<1	<1	<1

CONTAMINANTS



	method	limit/base	current	history1	history2	
Silicon	ppm	ASTM D5185(m)	>25	2	2	3
Sodium	ppm	ASTM D5185(m)		8	3	7
Potassium	ppm	ASTM D5185(m)	>20	<1	0	0
Fuel	%	ASTM D7593*	>3.0	0.7	<1.0	<1.0

INFRA-RED

	method	limit/base	current	history1	history2	
Soot %	%	ASTM D7844*	>4	0.6	0.1	0.4
Nitration	Abs/cm	ASTM D7624*	>20	9.2	5.4	7.5
Sulfation	Abs./1mm	ASTM D7415*	>30	21.1	18.5	19.8



OIL ANALYSIS REPORT



FLUID DEGRADATION

method	limit/base	current	history1	history2
Oxidation	Abs./1mm ASTM D7414*	17.3	13.7	15.3









VISUAL

method	limit/base	current	history1	history2
Emulsified Water	scalar Visual*	NEG	NEG	NEG
Free Water	scalar Visual*	NEG	NEG	NEG

FLUID PROPERTIES

method	limit/base	current	history1	history2
Visc @ 100°C	cSt ASTM D7279(m)	▲ 11.4	11.6	11.2

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **GFL Environmental - 747 - GMA - Solid Waste**
Sample No. : GFL0107624 **Received** : 28 Mar 2024 **4 Chemin du Tremblay,**
Lab Number : 02625171 **Tested** : 01 Apr 2024 **Boucherville, QC**
Unique Number : 5750290 **Diagnosed** : 01 Apr 2024 - Kevin Marson **CA J4B 6Z5**
Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel) **Contact: Steve Voyer**
svoyer@matrec.ca

To discuss this sample report, contact Customer Service at 1-800-268-2131. T:
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. F:
 Validity of results and interpretation are based on the sample and information as supplied.