




OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id

501032

Component

Diesel Engine

Fluid

PETRO CANADA DURON HP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

Metal levels are typical for a new component breaking in.

Contamination

Tests indicate that there is no fuel present in the oil. There is no indication of any contamination in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		GFL0117295	GFL0099528	GFL0084265
Sample Date	Client Info		02 May 2024	15 Dec 2023	05 Jul 2023
Machine Age	kms	Client Info	7176	43629	13503
Oil Age	kms	Client Info	150	0	0
Oil Changed	Client Info		Changed	Changed	N/A
Sample Status			NORMAL	NORMAL	NORMAL

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.2	NEG	NEG	NEG
Glycol	WC Method		NEG	NEG	NEG

WEAR METALS

	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m) >100	10	20	11
Chromium	ppm	ASTM D5185(m) >20	<1	2	<1
Nickel	ppm	ASTM D5185(m) >4	<1	2	<1
Titanium	ppm	ASTM D5185(m)	0	0	0
Silver	ppm	ASTM D5185(m) >3	0	0	<1
Aluminum	ppm	ASTM D5185(m) >20	2	6	4
Lead	ppm	ASTM D5185(m) >40	0	0	0
Copper	ppm	ASTM D5185(m) >330	1	3	2
Tin	ppm	ASTM D5185(m) >15	0	<1	0
Antimony	ppm	ASTM D5185(m)	0	0	0
Vanadium	ppm	ASTM D5185(m)	0	0	0
Beryllium	ppm	ASTM D5185(m)	0	0	0
Cadmium	ppm	ASTM D5185(m)	0	0	0

ADDITIVES

	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m) 0	3	20	296
Barium	ppm	ASTM D5185(m) 0	0	0	0
Molybdenum	ppm	ASTM D5185(m) 60	58	62	72
Manganese	ppm	ASTM D5185(m) 0	<1	0	<1
Magnesium	ppm	ASTM D5185(m) 1010	966	909	528
Calcium	ppm	ASTM D5185(m) 1070	1046	1131	1342
Phosphorus	ppm	ASTM D5185(m) 1150	986	1003	1091
Zinc	ppm	ASTM D5185(m) 1270	1160	1201	1181
Sulfur	ppm	ASTM D5185(m) 2060	2530	2560	2775
Lithium	ppm	ASTM D5185(m)	<1	<1	<1

CONTAMINANTS





	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m) >25	3	4	6
Sodium	ppm	ASTM D5185(m)	2	2	2
Potassium	ppm	ASTM D5185(m) >20	3	7	4
Fuel	%	ASTM D7593* >5	0.0	<1.0	<1.0

INFRA-RED

	method	limit/base	current	history1	history2
Soot %	%	ASTM D7844* >3	0.1	0.3	0
Nitration	Abs/cm	ASTM D7624* >20	6.4	8.5	5.5
Sulfation	Abs/.1mm	ASTM D7415* >30	18.7	19.6	18.9



OIL ANALYSIS REPORT











FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	14.4	16.0	13.1
Base Number (BN)	mg KOH/g	ASTM D2896*	9.8	9.41	10.21	7.44

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.6	12.1	13.6	13.3

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0117295
Lab Number : **02633852**
Unique Number : 5775005
Test Package : MOB 2 (Additional Tests: FuelDilution, PercentFuel)

GFL Environmental - 550 - Rocky View County
 220 Carmek Blvd
 Rocky View County, AB
 CA T1X 1X1
 Contact: GFL Calgary
 calgarymaintenance@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

T:
 F: (403)369-6163