


PROBLEM SUMMARY

Sample Rating Trend




Machine Id **7353**Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- QTS)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL	NORMAL					
Silicon	ppm	ASTM D5185m	>25	<u>44</u>	3					

Customer Id: PERSALMD Sample No.: PCA0088747 Lab Number: 05898308 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

20 Aug 2021 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. Please specify the component make and model with your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend





7353 Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- QTS)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

QTS)			Aug2021	Jul2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0088747	PCA0054990	
Sample Date		Client Info		04 Jul 2023	20 Aug 2021	
Machine Age	mls	Client Info		0	849470	
Oil Age	mls	Client Info		0	30000	
Oil Changed		Client Info		N/A	Changed	
Sample Status				ABNORMAL	NORMAL	
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Glycol		WC Method		NEG	NEG	
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	5	13	
Chromium	ppm	ASTM D5185m	>20	<1	<1	
Nickel	ppm	ASTM D5185m	>4	<1	0	
Titanium	ppm	ASTM D5185m		2	0	
Silver	ppm	ASTM D5185m	>3	0	<1	
Aluminum	ppm	ASTM D5185m	>20	1	0	
Lead	ppm	ASTM D5185m	>40	<1	1	
Copper	ppm	ASTM D5185m	>330	9	5	
Tin	ppm	ASTM D5185m	>15	<1	<1	
Antimony	ppm	ASTM D5185m			0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	14	16	
Barium	ppm	ASTM D5185m	0	2	0	
Molybdenum	ppm	ASTM D5185m	50	59	62	
Manganese	ppm	ASTM D5185m	0	0	<1	
Magnesium	ppm	ASTM D5185m	950	856	905	
Calcium	ppm	ASTM D5185m	1050	1152	1160	
Phosphorus	ppm	ASTM D5185m	995	1013	1043	
Zinc	ppm	ASTM D5185m	1180	1203	1198	
Sulfur	ppm	ASTM D5185m	2600	3418	2725	
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	44	3	
Sodium	ppm	ASTM D5185m		<1	2	
Potassium	ppm	ASTM D5185m	>20	1	<1	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.1	0.3	
Nitration	Abs/cm	*ASTM D7624	>20	5.5	7	
Sulfation	Abs/.1mm	*ASTM D7415	>30	17.9	19.3	
FLUID DEGRAD	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	13.2	14.4	
Base Number (BN)	mg KOH/g	ASTM D2896		9.7	9.1	



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

Unique Number

: PCA0088747 : 05898308 : 10559664 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jul 2023

Diagnosed : 17 Jul 2023 : Don Baldridge Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PERDUE FARMS - SALISBURY

7036 ZION CHURCH ROAD SALISBURY, MD

US 21802 Contact: RICHARD O'NEAL richard.oneal@perdue.com

T: (410)543-3628 F: (410)341-2164